

Accredited by NABL vide certificate Number TC-14728 D25, Ambattur Industrial Estate, Chennai – 600058.

Ph: 044-26242525/044-61740800 Email: cre@microlabtesting.com Web: www.microlabtesting.com





Test Report

Customer :	Report No.:	TRC - 17632-2	
M/s. Top Floor Sports Infra Private Limited.,	Report Date:	02-08-2025	
Survey No : 199, Vaghroda Village, Vaghroda,	Customer Ref. No.:	Letter	
Taluka: Kadi	Customer Net. No	(2)	
Pin code: 382715	Ref. Date	23-07-2025	
Contact Person : Lalit Sondarva	Sample Received Date:	19-07-2025	
E Mail ID: info@topfloorsportsinfra.com	Cample Received Date.		
Contact number: 9978631811	Date Of Completion:	02-08-2025	

Test Performed by: VINAY KUMAR T.V.

1) Sample details:

Sn	ltem	Description		
1	Name of the Sample	Acrylic Paint Testing		
2	Part No & Model	9 -		
3	Material			
4	Grade	8		
5	Lot No			
6	Material Tes <mark>t std</mark>	ISO 1518		
7	Test Item S	Scratch Resistance Test		
8	Lab sample ID number	TRC-17632		
9	Discipline	Paint Products		
10	Pre condition start Date & Time	01-08-2025 @ 10.00 AM		
11	Pre condition End Date & Time	02-08-2025 @ 10.00 AM		
12	Scratch Resistance Test Start Date & Time	02-08-2025 @ 10.00 AM		
13	Scratch Resistance Test End Date & Time	02-08-2025 @ 04.00 PM		
14	Sample drawn by	Customer		

NOTE: This report relates only to the particular sample submitted for test * Any correction is not attested shall invalidate this certificate * Sample will be destroyed after 15 days from the date of testing unless instructed otherwise * Any complaints about this report should be communicated in writing within 7 days of this report * This report not to be produced wholly or in parts and cannot be used as an evidence in a court of law and shall not be used in advertising Media without prior permission in writing * Sample description is not verified in all cases and is given as described by the customers * Sample are not drawn by us unless otherwise stated * Laboratory reports the statements of Conformity to material specification as per Decision Rule 1, Non Conformity as per Decision Rule 4 & For Rule 2 & 3 Customer provides feedback.





Accredited by NABL vide certificate Number TC-14728 D25, Ambattur Industrial Estate, Chennai – 600058. Ph: 044-26242525/044-61740800

Email: cre@microlabtesting.com Web: www.microlabtesting.com






TRC-17632-2 Dt-02-08-2025

Test Report

2) Received Sample Images:



3) Sample Preparation Image:



NOTE: This report relates only to the particular sample submitted for test * Any correction is not attested shall invalidate this certificate * Sample will be destroyed after 15 days from the date of testing unless instructed otherwise * Any complaints about this report should be communicated in writing within 7 days of this report * This report not to be produced wholly or in parts and cannot be used as an evidence in a court of law and shall not be used in advertising Media without prior permission in writing * Sample description is not verified in all cases and is given as described by the customers * Sample are not drawn by us unless otherwise stated * Laboratory reports the statements of Conformity to material specification as per Decision Rule 1, Non Conformity as per Decision Rule 4 & For Rule 2 & 3 Customer provides feedback...





Accredited by NABL vide certificate Number TC-14728 D25, Ambattur Industrial Estate, Chennai – 600058. Ph: 044-26242525/044-61740800

Email: cre@microlabtesting.com Web: www.microlabtesting.com





TRC-17632-2 Dt-02-08-2025

Test Report

4) General Condition:

Sn	Items	Description
1	Test Lab environment condition	Temperature : 23 ± 2°C & 50 ± 5% RH
2	Pre condition of specimen	Temperature: 23 ± 2°C and 50 ± 5 % RH for 7 Days
3	Qty of Sample	3 Nos.

5) Test Result Summary:

Sn Test Items		Test Method	Condition	Requirement	Observation		Result
				219	S1	No visible crack, gloss change observed after test	OK
1	Scratch Resistance Test	ISO 1518 - 1	Load – 500g speed -30 mm / min indented radius – 05 mm dia No of scratch -20		52	No visible crack, gloss change observed after test	ОК
					\$3	No visible crack , gloss change observed after test	ОК

NOTE: This report relates only to the particular sample submitted for test * Any correction is not attested shall invalidate this certificate * Sample will be destroyed after 15 days from the date of testing unless instructed otherwise * Any complaints about this report should be communicated in writing within 7 days of this report * This report not to be produced wholly or in parts and cannot be used as an evidence in a court of law and shall not be used in advertising Media without prior permission in writing * Sample description is not verified in all cases and is given as described by the customers * Sample are not drawn by us unless otherwise stated * Laboratory reports the statements of Conformity to material specification as per Decision Rule 1, Non Conformity as per Decision Rule 4 & For Rule 2 & 3 Customer provides feedback...





Accredited by NABL vide certificate Number TC-14728 D25, Ambattur Industrial Estate, Chennai - 600058. Ph: 044-26242525/044-61740800

Email: cre@microlabtesting.com Web: www.microlabtesting.com







TRC-17632-2 Dt-02-08-2025

Test Report

6) Test Sample Images:









Accredited by NABL vide certificate Number TC-14728 D25, Ambattur Industrial Estate, Chennai – 600058. Ph: 044-26242525/044-61740800 Email: cre@microlabtesting.com






TRC-17632-2 Dt-02-08-2025

Test Report

Web: www.microlabtesting.com

7) Test Equipment Images:



7.1) Scribe Tool Images:



NOTE: This report relates only to the particular sample submitted for test * Any correction is not attested shall invalidate this certificate * Sample will be destroyed after 15 days from the date of testing unless instructed otherwise * Any complaints about this report should be communicated in writing within 7 days of this report * This report not to be produced wholly or in parts and cannot be used as an evidence in a court of law and shall not be used in advertising Media without prior permission in writing * Sample description is not verified in all cases and is given as described by the customers * Sample are not drawn by us unless otherwise stated * Laboratory reports the statements of Conformity to material specification as per Decision Rule 1, Non Conformity as per Decision Rule 4 & For Rule 2 & 3 Customer provides feedback..





Accredited by NABL vide certificate Number TC-14728 D25, Ambattur Industrial Estate, Chennai - 600058. Ph: 044-26242525/044-61740800

Email: cre@microlabtesting.com Web: www.microlabtesting.com





TRC-17632-2 Dt-02-08-2025

Test Report

8) Test Equipment Details:

Equipment name	Model	Equipment ID	Calibrated date	Calibration Next Due
Automatic Scratch Tester Constant Load	BGD 520/2	PL/001/2025	15-11 <mark>-2</mark> 025	14-11-2025

9) Conformity:

The Scratch Resistance Test observation MEETS the customer requirement of ISO 1518 - 1.

For MICROLAB **B.Sudharsan** Technical Director **Authorized Signatory End of Test Report**

NOTE: This report relates only to the particular sample submitted for test * Any correction is not attested shall invalidate this certificate * Sample will be destroyed after 15 days from the date of testing unless instructed otherwise * Any complaints about this report should be communicated in writing within 7 days of this report * This report not to be produced wholly or in parts and cannot be used as an evidence in a court of law and shall not be used in advertising Media without prior permission in writing * Sample description is not verified in all cases and is given as described by the customers * Sample are not drawn by us unless otherwise stated * Laboratory reports the statements of Conformity to material specification as per Decision Rule 1, Non Conformity as per Decision Rule 4 & For Rule 2 & 3 Customer provides feedback..

